```
FILE 'REGISTRY' ENTERED AT 17:52:42 ON 15 JUN 2008
              1 SEA ABB=ON PLU=ON 25085-79-4
T.1
     FILE 'CAPLUS' ENTERED AT 17:53:08 ON 15 JUN 2008
L2
          13803 SEA ABB=ON PLU=ON L1 OR (?ETHYLENE (5A) MALEIC?)
            349 SEA ABB=ON PLU=ON L2 AND ((GAS OR OXYGEN OR O2 OR NITROGEN
L3
               OR N2) (10A) BARRIER)
     FILE 'REGISTRY' ENTERED AT 17:55:22 ON 15 JUN 2008
               E PVA/CN
L4
              2 SEA ABB=ON PLU=ON PVA/CN
               D 1-2
L5
              1 SEA ABB=ON PLU=ON 1309-42-8
              1 SEA ABB=ON PLU=ON 546-93-0
L6
             1 SEA ABB=ON PLU=ON 1305-62-0
1.7
               E CALCIUM CARBONATE/CN
              1 SEA ABB=ON PLU=ON "CALCIUM CARBONATE"/CN
\Gamma8
     FILE 'CAPLUS' ENTERED AT 18:01:48 ON 15 JUN 2008
         136681 SEA ABB=ON PLU=ON (L4 OR PVA OR ?VINYLALCOHOL OR ?VINYL-ALCOH
L9
               OL OR (?VINYL ALCOHOL))
L10
            170 SEA ABB=ON PLU=ON (L9 AND L3)
         119606 SEA ABB=ON PLU=ON L5 OR L6 OR L7 OR L8
L11
              7 SEA ABB=ON PLU=ON L10 AND L11
L12
L13
              7 FOCUS L12 1-
               D 1-7 ALL RN
        155622 SEA ABB=ON PLU=ON (L5 OR L6 OR L7 OR L8 OR ((MG OR MAGNESIUM
T.14
               OR CA OR CALCIUM) (10A) (HYDROXIDE OR CARBONATE)))
L15
              9 SEA ABB=ON PLU=ON L10 AND L14
              2 SEA ABB=ON PLU=ON L15 NOT L12
L16
               D 1-2 ALL RN
     FILE 'CAPLUS, WPIX, JAPIO' ENTERED AT 18:13:28 ON 15 JUN 2008
L17
              1 SEA ABB=ON PLU=ON JP2003025518/PN
L18
              1 SEA ABB=ON PLU=ON JP2003025518/PN
L19
             1 SEA ABB=ON PLU=ON JP2003025518/PN
     TOTAL FOR ALL FILES
L20
             3 SEA ABB=ON PLU=ON JP2003025518/PN
               D 1-3 ALL RN
L21
              1 SEA ABB=ON PLU=ON JP2002127324/PN
             1 SEA ABB=ON PLU=ON JP2002127324/PN
L22
             1 SEA ABB=ON PLU=ON JP2002127324/PN
L23
     TOTAL FOR ALL FILES
              3 SEA ABB=ON PLU=ON JP2002127324/PN
L24
               D 1-3 ALL RN
     FILE 'CAPLUS' ENTERED AT 18:16:26 ON 15 JUN 2008
       1214883 SEA ABB=ON PLU=ON ((ZN OR ZINC OR CU OR COPPER OR CUPROUS OR
L25
               CUPRIC OR CO OR COBALT OR FE OR IRON OR NI OR NICKEL OR AL OR
               ALUMINUM OR ZR OR ZIRCONIUM) (20A) (HALIDE OR CHLORIDE OR
               OXIDE OR HYDROXIDE OR CARBONATE OR ACETATE OR PHOSPHATE OR
               NITRATE OR SULFATE))
L26
             12 SEA ABB=ON PLU=ON L10 AND L25
L27
             10 SEA ABB=ON PLU=ON L26 NOT L15
```

D 1-10 ALL RN